Facilities Notice

Title: MacLaurin D Wing Pre-Construction Hazardous Materials Survey

Location: MacLaurin D Wing building interior and roof

Description: Facilities Management will be working with North West Environmental

Group Ltd. taking samples to identify any hazardous building materials in the building and on the roof in the MacLaurin Building D Wing.

Time frame: January/February, 2017

Facilities Management contact: Gord Shirley, Senior Project Officer

Email address: gshirley@uvic.ca

Phone: 250-472-5062